

OSA-5678-63

4 November

Dear Al:

Per our telecon it is decided that the neck seal in the full pressure suit is not desirable. All suits with the neck seal should be reconverted to the face seal and any present work to install the neck seal should be discontinued.

Request you modify suit by removing the vent air ring at the wrists and boot tops. When the suit for 1045 is returned please modify it likewise. We will wait for comments from the pilots on this mod before changing any other suits.

25X1A

Sincerely,

25X1A

DOCINT 119
NOV 11 1963
251181
251181